CURRENT STATUS

TOP SECRET

STATUS AS OF 0700 LOCAL MONDAY, 27 MAY 1963

25X1A

TOP SECRET

COPY VOF V

CURRENT STATUS AS OF 0700 LOCAL 27 MAY 1963

AIRCRAFT:	All traces of A-12 removed from crash scene	
	and placed under cover of hangar at Wendover	
	by late afternoon, Saturday, 25 May. Loading	
	aboard two C-124s; under way early Sunday,	
	26 May; Destination: All small	25X1A
	bits and pieces meticulously picked up and	
	boxed.	
PILOT:	General condition excellent; mild complaint	-
	of back pain; X-rays of back normal; Initial	
	diagnosis: probably a muscular tenderness.	
	(See 9672 for detailed description);	25X1A
	Declared fit after examination at	25X1A
	Follow-up X-rays scheduled in two	25X1A
	weeks. scheduled to return to	25X1A
	at noon Sunday, 26 May, to meet	25X1A
	investigation board.	
PRESS:	General Hubbard feels press situation is under	
	control. Monitoring of news media continues.	
	9680)	25X1A

Approved For Release 2006/01/10 : CIA-RDP71B00590R000200040007-4

INVESTIGATION BOARD:	Initial meeting held Sunday evening, 26 May,	
	at for purposes of organizing and	25X1A
	establishing procedures. (See 9686).	25X1A
	Proceedings to begin Monday, 27 May.	
ADDITIONAL:	All A-12s grounded by Colonel Ledford Sunday	
	night, 26 May, until further notice.	25X1A
	9686).	

TOP SECRET

WEATHER SUMMARY OF ACCIDENT AREA

TOP SERRE

WEATHER SUMMARY OF ACCIDENT AREA

1. The following weather information was compiled by for the accident of A-12 aircraft number 123 on 24 May 1963.	25X1A
a. General Forecast for	25X1A
An unstable airmass lies to the north and northwest of with a weak trough aloft. Thermal heating will trigger scattered cumulus activity from north by 1700Z. Clouds will increase rapidly to 10,000 feet broken by 1800Z with scattered cumulonimbus. Broken middle and high cloud layers from 13,000 to 34,000 feet ASL will occur after 1800Z.	25X1A 25X1A
b. Flight Forecast for A-12 Aircraft Number 123, Valid from 1700Z to 2000Z:	
10,000 feet ASL broken variable overcast, upper broken with scattered thunderstorm activity northwest of a line from Tops of all cirrus 34,000 feet ASL. Terminal forecast for 10,000 feet scattered, more than 15 miles visibility.	25X1A 25X1A
c. Pilot Reports: 1900Z - Area of the accident: Tops of clouds variable, 34,000 to 35,000 feet ASL. 2015Z - Base of clouds 10,000 feet ASL, lower in thunderstorms. With thunderstorms north of a line	25X1
1715Z to 1800Z - In Easy Fit Refueling Area: Cumulus cloud tops above 33,000 feet ASL. Top of cirrus 30,500 feet ASL.	
1540Z - Scattered cumulus south of an east-west line through bases 12,000 feet tops 14,000 feet. Broken cirrus tops 31.000 feet looks better	25X1
toward	25X1

- 1956Z 75 nm west south west of Hill AFB, a line of buildups tops 36,500 feet.
- 1925Z From Ely to Shafter to Bonneville a broken line of Cumulonimbus tops 13,000 feet.
- d. Surface Weather Observations at 1900Z:
 - Wendover: 4.500 feet scattered, estimated
 5,500 feet broken 14,000 feet broken,
 50 miles visibility, thunder reported.
 Thunderstorms west through northwest
 moving slowly eastward, lighting from
 cloud to ground. Rainshowers in the
 distance west through northwest.
 - Ely: Estimated 5,500 feet broken, 8,000 feet broken, 45 miles visibility. Cumulonimbus to the north. Freezing level 11,000 feet ASL.

TOP SECRET

TRANSCRIPT OF CONTROL CENTER LOG BOOK

		Approved For Release 20 (1997) SEURE RDP71B00590R000200040007-4	25X1A
	24 MAY	1963 Cont'd:	25X1A
25X1,		CALLED TO REPORT COL. WIMBERLY CONTACTED BY BOXER, BUT NO DEFINITE INSTRUCTIONS RECEIVED. REFERRED TO AFIGO-5 FOR AIRLIFT IF REQUIRED. REQUESTED TO HAVE COL. WIMBERLY CONTACT FOR FURTHER INSTRUCTIONS. TO CONTACT BOXER AND ADVISE TO EXPECT CALL AND TELL COL. WIMBERLY "WHEN AND WHERE" HE IS NEEDED. THIS PASSED TO BOXER CONTROL.	25X1A
25X1A	21232	CHECKED THRU SALT LAKE CITY CENTER REGARDING INFORMATION ON WENDOVER AUX AIRFIELD: 8500' HARD SURFACE, RADIO CONTACT TO THE WENDOVER FIRE TRUCK ON 245.6 OR 122.8. FURTHER INFORMATION CAN BE OBTAINED FROM	25X1A 25X1A
*	21402	PASSED (TELECON) ITEMS #6, 8 AND NEW DEVELOPMENT (HILL AFB PRESS AGENCY) TO COL. GEARY - LATER WILL HAVE CALL PIO AT HILL AND TELL HIM NOT TO RESPOND.	25X1A
	2155 Z	CALLED TO ADVISE THAT AFIGO-5 HAS CONTACTED GEN. COPELAND, C/G HILL DEPOT, TO RENDER ALL NECESSARY ASSISTANCE TO	25X1A
	2250Z	TELECON SHUT DOWN.	25X1A
	2315Z	TELECON OPENED (ITEM 26).	
	25 MAY	1963	
	0130Z	RECEIVED CALL FROM MR. Mc CONE'S SECURITY GUARD WHO ASKED IF WE HAD ANY ADDITIONAL INFORMATION - PASSED CONTENTS (TELECON) ITEM 30 TO MR. Mc CONE IN PERSON WHO SEEMED SATISFIED AND ASKED NOT TO BE DISTURBED UNLESS THERE IS A FLAP.	25X1A
	0230Z	CALLED REF COMMAND POST EXERCISE BRAVO. DELAYED TO EARLY JUNE. ADVISED	25X1A 25X1A
4	₩ 0230Z	NUMEROUS CALLS PERTAINING TO NEWS THAT SALT LAKE CITY TV HAS POSSIBLE PICTURES OF AND/OR CRASH ACTION. ATTEMPTING TO CALL M/GEN. MARTENS. NO SUCCESS. IS TALKING TO COL. LEDFORD WHO CALLED IN. RELAYED INFORMATION. DR. SCOVILLE NO LONGER AT THE PARTY AT THE MAYFLOWER.	25X1A
	03402	CALLED WEATHER CENTRAL FOR INFORMATION REGARDING WEATHER AT WENDOVER. TERMINALS AT WENDOVER AND HILL AFB FOR PERIOD COVERING TOMORROW 25 MAY 63. ALSO REQUESTED NELLIS AFB LOCAL AREA WEATHER FOR 25 MAY 63. WILL CALL BACK AS SOON AS INFORMATION IS RESEARCHED.	25X1A

	25 MAY	1963 Cont'd:
	0350Z	RECEIVED CALL FROM AT WEATHER CENTRAL. WEATHER FOR HILL AFB AND LOCAL AREA: 6000 SCATTERED 12000 BROKEN 15 MILES VISIBILITY WINDS 090 DEG 10 KNOTS GUSTS TO 15 KNOTS BY 1800Z. 6000 SCATTERED 12000 SCATTERED 15 MILES PLUS VISIBILITY WINDS 10 KNOTS. TOWERING CUMULUS IN VICINITY. PRIOR TO 1000Z. INTERMITT 4000 BROKEN 7000 OVERCAST 7 MILES VISIBILITY IN RAIN SHOWERS. WENDOVER AREA: 5000 BROKEN 8000 OVERCAST 10 MILES VISIBILITY IN LIGHT RAIN SHOWERS. NELLIS LOCAL AREA: 12000 SCATTERED 15 MILES VISIBILITY VARIABLE 8 TO 10 MILES BY 1800Z. SURFACE WINDS FROM 140 DEG 15 KNOTS GUSTS TO 20 KNOTS.
25X1A 5X1A		TELECON SHUT DOWN AND MESSAGE RECORD IS FILED IN OXC 123 FOLDER. MR. CUNNINGHAM REQUESTED THE DUTY OFFICER NOTIFY DR. SCOVILLE OF NEW DEVELOPMENTS AT 0800L. ALSO REQUESTED THAT IF CALLS, RELAY THAT HE SHOULD CALL MR. CUNNINGHAM
25X1A		AT HOME. (LAC JETSTAR IS SET TO DEPART ABOUT 0800L TO TAKE TO ALBUQUERQUE
25X1A		WILL REMAIN AT THE DESERT INN MOTEL UNTIL ORDERED BY HORS TO GO
X1A		TO) MR. CUNNINGHAM®S IMMEDIATE PLEASURE TO MEET WITH AT 1100L, SEE THE DCI AT 1200L AND BE PRESENT AT IDEALIST 152 GO-NO-GO BRIEFING AT 1300L. COL.
		PRESENT AT IDEALIST 152 GO-NO-GO BRIEFING AT 1300L. COL. LEDFORD PLANS TO DEPART ANDREWS AFB AT 0800EDT VIA T-33 FOR
5X1A X1A		VIA HILL AFB.
XI/X	0710Z	DR. SCOVILLE CALLED TO REPORT HE IS AT HOME IN THE EVENT OF NEWS.
	1030Z	COL. GEARY CALLED FOR AN UPDATING. I DEFERRED UNTIL A CALL TO BOXER CONTROL WAS MADE.
	1031Z	BOXER CONTROL QUIET. SECURITY)
25X1A	\	ON DUTY. THEY REPORTED: (A) THE C124 IS STILL AT NELLIS AFB, NOW PLANNING 1300Z TAKE OFF FROM NELLIS TO GO TO AND UNLOAD. PLAN TO TURN AROUND
:5X1A		AND FLY TO THE CRASH SITE. (B) GEN. ROBBINS WILL DEPART HILL AFB AT 1630Z BY H-21 FOR SITE.
25X1A		PEOPLE AND FOR SITE AT 12302 WITH MAINTENANCE
25X1A	4	(D) 2 FLAT BEDS PLUS 2 FIVE TON CRANES PLUS SIX OTHER TRUCKS DEPARTED HILL AFB AT APPROX 1000Z ENROUTE TO SITE.
5X1A		(E) IS CHECKING HILL REGARDING AVAILABILITY OF
25X1A	\	2 TWENTY TON TRUCKS. (F) JETSTAR WILL ARRIVE FROM BURBANK IN THE MORNING
5X1A		FOR A 1600Z DEPARTURE TO ALBUQUERQUE WITH
	10402	RELAYED TO HIM. HE WILL BE IN HIS OFFICE BY 1130Z AND WILL CALL THIS COMMAND POST FOR FURTHER INFORMATION. HE IS CONCERNED THAT ALL EFFORT BE EXPENDED TO REMOVE THE WRECKAGE FROM THE LANDSCAPE. HE IS CONCERNED THAT PRECIOUS HOURS OF DARKNESS ARE PASSING WITHOUT SUFFICIENT EFFORT FOR RAPID DAYLIGHT MOVEMENT AT WENDOVER.
		TAN AFARET

Approved For Release 100 GIRET CIA-RDP71B00590R000200040007-4

25 MAY	1963 Cont'd:
25X1A 25X1A 25X1A 25X1A 25X1A 25X1A 25X1A	CALLED TO REPORT: (A) THE FIRST LOAD OF WRECKAGE SHOULD BE READY FOR PICKUP AT WENDOVER AT APPROX 1900Z AND ENTIRE JOB WILL TAKE FOUR LOADS. (B) HE SUGGESTS SECOND C124 COULD BE USED AT APPROX 1800Z. (C) SUFFICIENT OLD HANGER BUILDINGS EXIST AT WENDOVER TO HOUSE THE WRECKAGE AS IT IS BROUGHT IN. (D) NO NIGHT OPERATIONS ARE PLANNED, THE TRUCK ROUTE IS DANGEROUS. REQUIRES A 40 MINUTE DRIVE. (E) WILL RETURN TO THE SITE WITH THE C121 ESTIMATED TIME OF DEPARTURE FROM IS 1230Z. WILL REMAIN AT
	BOXER CONTROL REPORTED THE FOLLOWING SUPPORT FROM HILL AFB: 4 - 6 PASSENGER PICKUPS, DEPARTED HILL 0630Z. 1 - WEAPONS CARRIER, DEPARTED HILL 0630Z. 2 - 40' FLAT BEDS, DEPARTED HILL 1020Z. 2 - 1½ TON PLATFORM TRUCKS, DEPARTED HILL 1020Z. 2 - 5 TON RIGGERS, DEPARTED HILL 1020Z. 1 - 6000 LB FORK LIFT, DEPARTED HILL 1020Z. 3 - F-2 TRAILERS, DEPARTED HILL 1020Z. 4 - 5 TON TRUCKS, DEPARTED HILL 1200Z.
1115Z 25X1A	COL. LEDFORD CALLED FOR A STATUS. HE CONCURRED ON USE OF SECOND C124 IF NECESSARY. HE WILL DEPART ANDREWS SHORTLY ENROUTE HILL AFB AND
1125 Z	BOXER CONTROL REPORTS: (A) WENDOVER BASE MANAGERS OFFICE CAN BE REACHED BY COMMERCIAL CALL: WENDOVER 2171 FIRE CHIEF PALINER. (B) SITE PARTY OF APPROX 25 IS CONTACTED BY RADIO FROM OVERHEAD AIRCRAFT. NO CONTACT SINCE DARKNESS LAST NIGHT.
11352	DR. SCOVILLE WILL BE IN, IN 15 MINUTES FOR A RECAP. MR. Mc CONE WILL GET A REPORT AT 0815L BY DR. SCOVILLE.
¥ 11552	COL. GEARY REQUESTED: (A) PLACE FOR SECOND C124 TO BE DISPATCHED TO. (B) THAT 2 OR 3 AIR POLICE BE PLACED IN THE SITE OF THE WRECKAGE IN ORDER TO MATCH COVER STORY OF AIR FORCE WRECKAGE.
1200 Z 25X1A	BOXER CONTROL REPORTS! (A)REQUESTS SECOND C124 GO DIRECT TO WENDOVER AND STANDBY. (DESIRED ESTIMATED TIME OF ARRIVAL AFTER 2200Z) (B) ONE 0-11 FIRE TRUCK AVAILABLE AT WENDOVER. (C) ONE H-21 HELICOPTER WILL BE AVAILABLE. (D) ONE FUEL TRUCK FOR THE HELICOPTER.

Approved For Release 7905/01/10 PPA-RDP71B00590R000200040007-4

		IOL SEEVEL	
	25 MAY	1963 Cont'd:	
	25X1A	COL. GEARY REPORTS: (A) KENT (TV) COOPERATIVE WITH GEN. HUBBARD NO PROBLEM. (B) INQUIRED ABOUT SECURITY. WAS TOLD THAT ONE AIR POLICEMANT FROM HILL AFB HAD BEEN RELEASED. COL. GEARY VERY DISTURBED AND INSISTED THAT AIR POLICEMAN BE REPLACED. THIS WAS RELAYED TO	ND .
2	1220Z 25X1A 25X1A	CALLED AND ASKED FOR TO CALL HIM REF: ARRANGEMENTS HAD TALKED TO MR. CUNNINGHAM. PASSED THE REQUEST TO BOXER CONTROL.	0574
	1230Z 25X1A	DR. SCOVILLE RETURNED FROM DCI'S OFFICE AFTER 5 MINUTE REVIEW WILL GO TO MR. BUNDY'S OFFICE AND THEN RETURN. HE ASKED FOR CHRONO FILE ON PRESS-SECURITY-COVER DETAILS TO BE MAINTAINED.	A
	1245Z	REVIEWED CURRENT STATUS.	
	★ 1300Z	BOXER CONTROL RELAYED: (A) REQUESTS COL. GEARY RECONSIDER AIR POLICE BECAUSE:	
	25X1A 25X1A	(1) NO PUBLIC ARE IN THE AREA. (2) THE SITE IS VERY REMOTE. (3) ONLY 1 AIR POLICEMAN HAS BEEN INVOLVED UP TO NOW. HE HABEEN DEBRIEFED AND RELEASED. HE IS NOT NECESSARY AND PROJECT SECURITY CAN ADEQUATELY HANDLE SITUATION. (4) THE LESS AIR POLICE INVOLVED THE BETTER FROM PROJECT	.s
	25X1A X1 25X1A 25X1A	SECURITY AND DEBRIEFING POINT OF VIEW. (B) REPORTS HE VISITED WHO WAS MOST COOPERATIVE. CONFISCATED ALL NEGATIVES/PICTURES AND FOUND COOPERATIVE IN ALL ASPECTS EXCEPT HE WOULD NOT REVEAL HIS PRIVATE PILOT'S NAME FOR FEAR OF PUNISHMENT FOR FLYING WITHIN A RESTRICTED AREA. (C) WAITING FOR C121 FROM WITH MAINTENANCE PEOPLE.	25X1
	25X1A	AFTER CHECK WITH COL. GEARY, PASSED TO THAT 2 OR 3 AIR POLICE SHOULD BE IN PLACE. ALSO THAT PILOT NAME SHOULD BE DETERMINED. PROTECTION FROM PUNISHEMENT IF THE NAME IS REVEALED. PUNISHMENT GUARANTEED IF WE HAVE TO TRACK HIM DOWN.	25X1
	1325Z 25X1A 25X1A	COL. GEARY CALLED FOR DETAILS OF PILOT NARRATIVE. HE ASKED FOR BRIEF, NOT SATISFIED SINCE IT WAS SKETCHY. HISIS NOT OPEN, SO WE WILL COURIER A COPY OFNARRATIVE.	
	1330 Z	MR. CUNNINGHAM CALLED TO REPORT: (A) KELLY JOHNSON CALLED HIM TO REPORT HE WOULD BE OUT OF HI OFFICE THIS AM BUT IN HIS OFFICE AFTER LUNCH. (B) THE JETSTAR REQUIRED A NOSE WHEEL TIRE CHANGE BECAUSE OF RUNWAY CONDITION AT WENDOVER. PLEASE RELAY TO OTHER AIRCRAFT OPERATING INTO THERE. (C) MR. CUNNINGHAM WILL BE IN AT 1100L.	,
		Approved For Release 20 (5) / 1 9 (20) - RDP71B00590R000200040007-4	

25 MAY	1963 Cont'd:	25X1A
1335Z	PILOTS NARRATIVE TRANSMITTED TO COL. GEARY VIA COL. GEARY IS WITH	25X1A
14552	PASSED CREW AND AIRCRAFT NUMBER FOR AIRLIFT TO WENDOVER.	25X1A 25X1A
	AIRCRAFT COMMANDER.	25X1A
	ENGINEER. ENGINEER.	25X1A
	THIS CREW WILL DEPART TRAVIS AFB 20/1410Z (THIS TIME ENTERED IN THE CONTROL CENTER LOG IN ERROR. TIME SHOULD READ 25/1415Z) FOR THIS AREA FOR FURTHER INSTRUCTIONS.	
1518Z	THE ABOVE INFORMATION PASSED TO	25X1A
1550Z	 (A) FIRST C124 NOW UNLOADING. (B) C121 ESTIMATED AT WENDOVER 1535Z. (C) MOTOR VEHICLES FROM HILL AFB ALL IN PLACE EXCEPT DUMP TRUCH 	25X1A
	THIS INFORMATION PASSED TO AFIGO-5,	25X1A
1555Z	CALLED FOR STATUS OF SUPPORT EQUIPMENT: (A) FIRST C124 NOW UNLOADING. (B) C121 ESTIMATED AT WENDOVER 1535Z. (C) ALL MOTOR VEHICLES FROM HILL AFB IN PLACE EXCEPT THE DUMP TRUCK. THIS INFORMATION RELAYED TO AFIGO-5.	25X1A 25X1A
1605Z	CONCURS THAT THE SECOND C124 (FROM TRAVIS AFB)	20/1/
	SHOULD BE DISPATCHED DIRECT TO WENDOVER. (A)(PILOT OF FIRST C124) WILL BRIEF SECOND C124 ON NORTHEAST ENTRY PROCEDURES. (B) RUNWAY AT WENDOVER EXTREMELY ROUGH.	25X1A
	(C) NO FUEL OR ADI AVAILABLE. (D) 245.6 OR 122.8 ARE AVAILABLE. CALLED AND RELAYED ABOVE INFORMATION FOR RELAY TO TRAVIS AFB. EXPECTED DEPARTURE FROM TRAVIS AFB 1815Z.	25X1A
		25X1A
1710Z	RECEIVED CALL FROM C124 AIRCRAFT HAS BEEN ADVISED OF ABOVE ENTRY AND HE HOPES THEY GET TOGETHER.	25X1A
1 8152	CALLED DR. SCOVILLE PER REQUEST ON ARTICLE APPEARING IN LAS VEGAS REVIEW JOURNAL OF INCIDENT. DR. SCOVILLE STATED HE WOULD LIKE ONE COPY GIVEN TO AND HE WOULD NOT NEED ANY EXTRA COPIES FOR HIMSELF.	
		25X1A

Approved For Release 100 CTT DE CIA-RDP71B00590R000200040007-4

25X1A 25X1A

		25 MAY	1963 Cont'd:	_	
	*	_18562	CALLED IN REFERENCE TO MESSAGE REGARDING ARTICLE APPEARING IN LAS VEGAS REVIEW JOURNAL. I TOLD HIM I HAD THE MESSAGE THAT QUOTED THE ARTICLE VERBATIM. SAID THAT HE HAD SEEN THE ONE THAT GAVE THE JEST OF THE CONTENTS AND THAT THE DIRECTOR HAD BEEN INFORMED AND THAT HE WOULD NOT HAVE TO THIS ONE AT THE PRESENT TIME.	AT	
		194 0Z	RECEIVED CALL FROM COL. LEDFORD FROM ALBUQUERQUE. HE TALKED MR. CUNNINGHAM. MR. CUNNINGHAM BRIEFED HIM ON THE SITUATION TO THIS POINT.	го	
		19432	PASSED TO BOXER CONTROL: COL. LEDFORD ESTIMATING YOUR STATION 1500PST.	N	
		26 MAY	1963	2	25X1A
2	5X1A		CALLED BOXER CONTROL		25X1/ 25X1/
	*	1555Z	CALLED REF MESSAGE (9679 IN 77728) REPORTING CONJECTURE LOCAL PRESS THAT PILOT'S NAME AND MISSION NOT RELEASED BY USAF. SECURITY, PER REF, TO FORWARD DETAILS TO BRIEFED CONTENTS OF REF MESSAGE.	3	25X1/ 25X1/ 25X1/ 25X1/
	*	1810Z	RELAYED CONTENTS 9680) TO COL GEARY. HE HAD HEARD OF THESE ARTICLES FROM WHO HAD TALKED TO GEN HUBBARD. GEN HUBBARD TOLD HE HAD NOT REFUSED TO IDENTIFY PILOT. HE HAD NOT BEEN ASKED FOR HIS IDENITY. IS GOING TO CALL THE NELLIS PIO AND DISCUSS THE POSSIBILITY OF VOLUNTEERING PILOTS NAME TO LAS VEGAS PRESS. COL GEARY HAS ARRANGED FOR TO CONTACT WRIGHT-PATTERSON TO INSURE AGAINST ANOTHER NEGATIVE RESPONSE SHOULD WRIGHT-PATTERSON HAVE AN INQUIRY REGARDING ALLEGED F105 ASSIGNMENT. IF THERE IS ANOTHER QUERY. QUESTIONER WILL BE REFERRED TO AFLC WHICH, OTHER THAN AFSC HAS RESPONSIBILITY FOR ALLEGED BAILED F105.	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	25X1/ 25X1/ 25X1/ 25X1/ 25X1/ 25X1/
	*	1840Z	PASSED PRECEEDING TO DDR WHO FELT WE MIGHT BE BETTER ADVISED NOT TO VOLUNTEER PILOT IDENTITY. HOWEVER THE DCI HAS APPROVER RELEASING THIS IF SITUATION DICTATES.	D	

Approved For Release 2006/21/10: CIA-RDP71B00590R000200040007-4

26 MAY 1963	20/11
BY GEN STROTHERS. POSSIBLE INQUIRY SU GEN DISAWAY WHO HAS ALSO BE ALERTED. C THAT IF IT NOT ALRE "ABSTRUSIVE" SEARCH SECURITY CIVILIANS	ACTED COL GEARY REF LOSS OF PILOTS ICH INCLUDED \$1000 AND LETTERS SIGNED REQUESTED GENSTROTHERS BE ALERTED TO BJECT LETTERS. ALSO RECOMMENDED THAT REPLACED GEN STROTHERS AS USAF DCS/OPS OL GEARY AGREES. COL GEARY RECOMMENDED ADY UNDERWAY, THAT INITIATE
GEARY'S RECOMMENDAT	UE SUITERS IN AIR FORCE VEHICLE. COL 25X1A
2300Z CALLE	D AND WANTED MSG (9683 IN77737) 25X1A
RELAYED TO MR CUNNI	NGHAM, 25X1A
RELAYED BY	
	25X1A

EMERGENCY PROCEDURES FOR NON-OPERATIONAL A-12 FLIGHTS

PROJECT DIRECTIVE

50-3055-4

Approved For Release 2000 P/15 EGR RDP71B00590R000200040007-4

SUPPLEMENT I PROJECT HEADQUARTERS DIRECTIVE 50-3055-4

OPERATIONS 14 MARCH 1963

EMERGENCY PROCEDURES FOR NON-OPERATIONAL A-12 FLIGHTS

TOP SECRET

ALASKA

The emergency procedures in support of A-12 operations within the Alaskan area will follow the provisions of Project Directive 50-3055-4 (ZI Emergency Procedures) as applicable. Certain additional information and procedures required for Alaskan operation are contained within this supplement. formation herein is with reference to the basic directive.

II. SCOPE

These procedures apply to the following:

B.

C.

Alaskan NORAD Region

V. PILOT PREFLIGHT BRIEFING

Pilots will be briefed prior to each flight regarding the following:

> 1. 2.

Emergency Packet:

Letters of Introduction:

(a)

(b)

To USAFB Commanders in Alaska (Attachment #1).

> OXC 4398/Rev.1 Copy // of /4 Page / of s

Approved For Release 200007105 ECARTO 71B00590R000200040007-4

(e) To Whom It May Concern In Alaska (Attachment #2).

		(Accaemment 42).		
VI.	DEF	<u>INITIONS</u>	3	
25X1A	A. B. C. D.			
5X1A the	E.	is the assigned call Command Post via Single Side Band comm	. sign for munications.	
VII	. <u>A-1</u>	2 INFLIGHT EMERGENCIES	•	
25X1A	Α.	EMERGENCY LANDING AT OTHER THAN		
•		1. PILOT PROCEDURES:	•	
	·	a.		
		(1) Priority 1: NORAD facility	y (UHF Frequenc	cy).
25X1A		(2) Priority 2: FAA facility (UHF Frequency).	(ARTCC)	
		Single Side Band.	nd Post via	
	D.	LOSS OF TWO-WAY RADIO COMMUNICATIONS		
•• •	,	1. a. Situation permits returning to [
25X1A 25X1A	· · · · .	(1) Circumstances permitting, directly to the terminal fix at enter the established holding patte appropriate altitude.	and	
		(a) In the event deviation coastal ADIZ penetration time e minutes or twenty miles, the IF turned on when passing:	xceeds fifteen	
		1. 5200 N on Pink or		
•		2. 7330N on Purple r		*.
25X1A		Coding will be as and coordinated wi submission of the Ad	th NORAD durin	ıg
25X1A			••	
	9 A	Copy_/	98/Rev. 1 / of /4 ~ of <u>/</u>	

	E.	AND CO ACREON (TANDE TOWN TO COMPANY)	ION SEUKET
25X1A	•	ANR CC ACTION (INFLIGHT EMERGENCY) L. Upon recipt of a	message:
, and the	, , . 	a. The AC&W or Dew Line site immediately pass message to ANR CC assistance in vectoring and cleari	Stand by to render
	. 1	b. ANR CC will immediately pa	ss message to
. •	E-1.	NORAD ACTION (INFLIGHT EMERGENCY):	•
, :		a. Notify Boxer Control.	
х.	SEAR	CH AND RESCUE PROCEDURES	
		NORAD COC ACTION:	
\bigcirc	1	a. b. Direct communications sear acilities through the Alaskan NOR	ch of military AD Region (ANR CC).
	A	c. Direct search and rescue a NR CC. (Pass the identical message oxer Control).	ction through the as received from
25X1A	r	d. Immediately relay all eceived to Boxer Control.	messages
•	4	. ANR CC ACTION:	
r	t	a. Notify Alaskan Rescue Cont he following actions:	rol Center to perform
		(1) Conduct communication military facilities.	s search of
25X1A	•	(2) Conduct search and re	scue actions.
	В	b. Immediately relay all oxer Control through NORAD if time	messages to allows. If
· · · · · · · · · · · · · · · · · · ·			OXC 4398/Rev 1

Applored Parkerses 2007/01/20 SE/ARPI71B00590R000200040007-4

necessary, direct voice communications may be established between the receiver site and Boxer Control. In this event ANR CC and NORAD will monitor the call.

TOP SECRET

5. ALASKAN AIR RESCUE CENTER ACTION:

25X1A

- a. Immediately conduct communications search for ______ traffic and advise ANR CC.
 - b. Alert SAR search force.
- c. Appoint mission commander from ARCC and maintain mission operational control.
- d. Conduct search and rescue as directed by ANR CC.
- e. Brief SAR aircrews that no operational reports will be made until aircraft sighting has been made. Upon making an aircraft sighting, the SAR crew will be briefed to contact the nearest ANR AC&W site and request the sighting information be passed to ANR CC. Sample message follows:

25X1A

- "Between Control, this is AF 46172. This is a message. Pass to ANR CC (nature of sighting, position, time, condition of aircraft, crew members, etc.)."
- f. If aircraft sighting is made in an inaccessible area, the ARCC will provide for the security of the aircraft and assistance to crew members.

XI. INCIDENT/ACCIDENT REPORTING AND INVESTIGATION

Α.

В.

C.

D.

E.

F. All incidents/accidents will be handled as directed by Project Headquarters. Normal requirements as outlined by AFR 127-4 are waived except as may be specified at the time of the accident.

OXC 4398/Rev.1 Copy // of // Page // of //

Approved For Release 200600110SE0041DF71B00590R000200040007-4

JUL SECRET

JACK C. LEDFORD Colonel USAF

OFFICIAL 25X1A (Signed) 25X1A Lt. Colonel USAF Attachments: #1 - Pilot Instructions #2 - Letter of Introduction (To USAFB Commanders in Alaska) #3 - Letter of Introduction (To Whom It May Concern In Alaska). 25X1A Distribution. #1, 2, 3 **-** [#4 - NORAD (Director COC) #5 - AAC (DCS/O) #6 - AFIGO-S #7 - OSA/C/OD #8 - OSA/OD/CC #9 - OSA/SEC #10 OSA/ 25X1A #11, 12, 13, 14 - OSA/OD/OXC

> OXC 4398/Rev.1 Copy // of /4 Page v of v

PILOT INSTRUCTIONS BRIEFING

	1	. Situations:	The	situations	in	which	guidance
may	bе	required are:		•			•

יי אנוגר אוצר אנוגר אנוג

b.

c.

- d.
 e. Emergency landing at an Alaskan USAF base.
- f. Emergency landing at an Alaskan civilian base.
- g. Bailout over the Alaskan area.

2. General Instructions:

a.

b.

c.

α.

е.

g. If within the ZI or Alaskan areas, press inquires will be referred to the Director of Information, Office of the Secretary of the Air Force, Washington, D. C.

3. Detailed Instructions:

- 4. Telephone Instructions: In any situation requiring unscheduled launching or bailout in the Alaskan area, telephone and advise the Alaskan Air Command Duty Officer, Elmendorf AFB at the following number:
 - a. 752-1302 or 752-1303
 - b. Furnish him with the following:

(1) Your location.

(2) Location of aircraft.

(3) Nature of the trouble.

(4) Assistance required.

(5) Telephone number where you can be reached for further information

(6) Known newspaper knowledge or interest.

OXC 4398/A,Rev.1 Copy_//of_/4 Page__/of_/_

ATTACADE NO Release 2001/0/10 SEG-RET71B00590R000200040007-4

HEADQUARTERS ALASKAN COMMAND

I'UI' JEUKE!

TO: U.S. AIR FORCE BASE COMMANDERS IN ALASKA

- 1. The bearer of this letter is engaged in a highly classified research program of the highest military interst. You will immediately take maximum precautionary measures to minimize public exposure of the aircraft. Names of personnel involved in this emergency will be recorded.
- 2. No information regarding this emergency will be released to the news media. If necessary, inquiries received for information will be referred to the Director of Information, Office of the Secretary of the Air Force, Washington, D. C.
- 3. You are requested to immediately telephone the Alaskan Air Command duty officer, Elmendorf AFB, at the following number:
 - a. 752-1302 or 752-1303
 - b. Furnish him with the following:
 - (1) Location and condition of the pilot and aircraft.
 - (2) Security of the aircraft.
 - (3) Assistance required.
- 4. Your careful attention to these instructions is vital to the national interest.

GEORGE W. MUNDY Lt. General, USAF Commander-in-Chief

> OXC 4398/B, Rev.1 Copy_// of_// Page__/ of_/

HEADQUARTERS ALASKAN COMMAND

TO WHOM IT MAY CONCERN IN ALASKA

TOP SECRET

The bearer of this letter is engaged in a highly classified research program for the United States Air Force. You are requested and this is your authority to take the following action:

- 1. Provide the pilot with necessary food, clothing, medical and/or other emergency care.
- 2. Call both the nearest law enforcement officer and the nearest Air Force Base Commander and give the latter all of the information you have regarding this incident. Request both to dispatch personnel to assist you in:
 - a. Maintaining maximum security of the aircraft, and
 - b. Rendering such other aid as may be necessary.
- 3. Call collect: The Air Force duty officer at Headquarters, Alaskan Air Command, Elmendorf Air Force Base, telephone numbers 752-1302 or 752-1303. If possible the following information should be given during this telephone call:
 - a. Name of Air Force Base notified.
 - b. Location of pilot and aircraft.
 - c. Condition of pilot and aircraft.
 - d. Assistance required.
 - e. Telephone number at which you can be reached for further information.
- 4. Provide guards for the aircraft and issue instructions to discourage anyone from inspecting or photographing the aircraft, or related equipment. Inquiries regarding the release of information to the various news media should be directed to the Director of Information, Office of the Secretary of the Air Force, Washington, D. C.

OXC 4398/C, Rev.1 Copy_// of_// Page_/_of_//

Approved FeeRelease 2016/01/2166/01/21800590R000200040007-4

5. Keep a record of the money you are required to spend in furnishing the above assistance and you will be repaid by the U.S. Air Force.

. VLUNLI

6. Upon the arrival of a military authority or a law enforcement official, you are requested to give him this letter and all other material pertaining to this matter. After accepting this letter, he is in charge of the incident.

GEORGE W. MUNDY Lt. General, USAF Commander-in-Chief

> OXC 4398/C, Rev. 1 Copy_// of_// Page__/ of__/

THIS DOCUMENT REQUIRES SPECIAL HANDLING

HANDLING PROCEDURES

THIS DOCUMENT CONTAINS INFORMATION REGARDING A HIGHLY CLASSIFIED ACTIVITY. PERMISSION TO TRANSFER CUSTODY, OR PERMIT ACCESS TO THIS DOCUMENT MUST BE OBTAINED FROM THE ORIGINATOR. HAND CARRY PROCEDURES WILL BE APPLIED TO ANY INTER-OFFICE OR INTRA-AGENCY MOVEMENT OF THIS DOCUMENT.

This document contains information referring to Project OXCART

REFERRED TO.	RECEIVED			RELEASED		SEEN BY			
OFFICE	SIGNATURE	DATE	TIME	DATE	TIME	NAME AND OFFICE SYMBOL	DATE		
OSA/OD/OX	С	 - -		1					A. A
				†					
				 				-	
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			ļ				-	
				<u> </u>					

TOP SECRET

Approved For Polosso 2006/01/10 - CIA PDP74P00500P000300040007

FORM 1352a